RJM Corporation
Ten Roberts Lane
Ridgefield, CT 06877
203 438-6198

RJM

FACSIMILE TRANSMITTAL COVER SHEET

DATE: _9/5/91_   FAX NO.: _____

Please deliver the following pages to:

COMPANY: _IPSC_   NAME: _Aaron Nissen_

REFERENCE: _____

THIS FAX IS FROM: _Richard Monro_

Number of pages _2_ (including cover sheet) transmitting from Xerox Telecopier
7032 (telephone 203 431-8255)

MESSAGE:

If you do not receive all the pages, please call back as soon as possible. 203-438-6198.

IP7_003318

MEMORANDUM

TO:　　　Mr. Aaron Nissen, Intermountain Power Service Corporation

FROM:　　Mr. Richard J. Monro, RJM Corporation

DATE:　　September 5, 1991

RE:　　　Request for Additional Information

---

1. The outer air door position and the inner air door position measurements are unclear. Please provide a drawing showing how measurements are taken.

2. What is the air door and air vane position when the burners are out of service?

3. What is the airflow through out-of-service burners?

4. Could you provide more temperature data on the outer furnace register backplates? What is the maximum temperature you have experienced? What was the burner setup condition? Were the burners in or out of service?

5. Photographs of the burners and burner damage would be very helpful in our analysis.

6. How many times are burners cycled in and out of service per day?

Please respond immediately. Thanks.
/ftd
E:\WPDOCS\IPSCAN2MEM

RESPONSE:

RJM Corporation · Ten Roberts Lane, Ridgefield, CT 06877 · 203 438-6198 · Fax 203 431-8255

IP7_003319